



GARY R. HERBERT
Governor


GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
February 06, 2013

Reviewed: 

Mine Name: Browns Canyon Rock Quarry	Permit Number: M/043/0021
Operator Name: Browns Canyon Stone Works	Inspection Date: September 8, 2010
Inspector(s): L Heppler	Time: 10:00 AM
Other Participants: Operators Representative	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 12-09-2009 **Bond Amount:** \$85,900 **Permit fee** is up to date for 2012, 2013 fees are being processed

Purpose of Inspection: Routine annual Inspection. This site was inspected as a large mine site on 05-20-2009.

Inspection Summary: At the time of the inspection, BMW Stone had not transferred the permit. Reclaimed area has not established vegetation, except for weeds.

Photos were taken to document site conditions.

Conclusions and Recommendations: Permit NOI needs to be updated based on current disturbance on the ground and the Operators plan. Weeds need to be controlled, as shown in attached photos. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:eb

cc: Browns Canyon Rock Quarry - Jim Sorenson

O:\M043-Summit\M0430021-BrownsCynRock-BMW\inspections\Insp-09082010.doc





Overview



Dumps in foreground and crushing area in the background



Crushing area



Reclaimed area